Oil Field Environmental Incident Summary

Responsible Party: ONEOK Rockies Midstream **Well Operator:** ONEOK ROCKIES MIDSTREAM

Well Name: SW of Meridian 34-33H

Field Name: Well File #:

Date Incident: 6/1/2015 Time Incident: 12:00 Facility ID Number:

County: BILLINGS Twp: 143 Rng: 102 Sec: 33 Qtr:

Location Description: Approximately 0.2 miles Southwest of Meridian 34-33H

Submitted By: Jason Lyons Received By:

Contact Person: Jason Lyons

2700 Lincoln Ave Sidney, MT 59270

General Land Use: Badlands Terrain Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

An estimated 1 cubic foot of dry, natural gas was released.

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There were no immediate risks to human health or the environment.

Areal Extent:

Approximately 15 feet by 15 feet area of suppressed vegetation at surface.

Potential Environmental Impacts:

There were no observable impacts to surface water or groundwater.

Action Taken or Planned:

The active line in the area was immediately isolated. One Call is underway.

Wastes Disposal Location: Recovered wastes will be disposed in accordance with applicable

State/Federal regulations.

Agencies Involved: U.S. Forest Service - Carmen Waldo

Updates

Date: 6/3/2015 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, impacted areas off location. Follow-up is required.

Date: 7/23/2015 Status: Inspection Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 15:30 p.m. The weather was cloudy, 84°F, with the wind from the southwest 10-15 mph. The area is on the west side of lease road. This area has been scraped up. No vegetation growing yet. More follow-up needed. 47.15273, -103.61540